

SIDUMATA SEGUDE TERASTIKULINE KOOSTIS

Pos.	Segu	Kasutus	Sõela ava mõõt, mm											
			80	63	40	31,5	20	16	8	4	2	1	0,5	0,063
			Läbib sõela, massi-%											
1	0/31,5	Sideainega töötlemata alus			100	85-99	-	58-70	39-51	26-38	17-28	11-21	5-15	0-5
2	0/31,5				100	85-99	-	54-72	33-52	21-38	14-27	9-20	5-15	0-5
3	0/63		100	85-99	-	58-70	-	39-51	26-38	17-28	11-21	5-15	-	0-5
4	0/63		100	85-99	-	63-77	-	33-52	21-38	14-27	9-20	-	-	0-5
5	0/16	Kruuskate ja tugi- peenar			-	-	100	85-99	65-90	50-75	35-60	20-45	10-35	8-15
6	0/31,5				100	85-99	-	60-80	40-65	30-55	20-45	10-30	8-20	8-15

Märkus: Sideainega töötlemata alustes määratakse terastikuline koostis valmishetatud alusest võetud materjali proovist.